

**Figure 1**




Figure 2




Figure 3






Figure 4





**Figure 5**




Figure 6a




Figure 6b





Figure 7

Figure 8







Figure 9

Figure 10a






Figure 10b




Figure 11a





Figure 11b

Figure 12






Figure 13

335      380      335      321      285      321

**Detailed information for defect: 3305**

Troubleshooter:	Kazem1_Niskam
Defect Category:	Component Defects
RD(s):	XERE , EEE
Comment:	
Reworker:	Kazem1_Niskam
Action Category:	Components
RD(s):	
Comment:	


Problem was not fixed

This box is to provide the system with feedback on whether the problem with the item has been fixed or not. This information is being checked when closing the quality ticket. If the quality ticket contains a defect with no corresponding action showing 'Problem was fixed' the ticket cannot be closed.

322      323      324      350      366

Figure 14

Figure 15



The following is a list of the most likely causes for the specified SYMPTOM

Defect Category	Defect	Frequency
Component Defects	Defective Component	58
Testing Defects	Test Error	51
Component Defects	Damaged	26
Fiber Defects	Broken Fiber	11
Connector Defects	Pitted	10
Solder Defects	Insufficient Solder	8
Testing Defects	High Insertion loss	6
Solder Defects	Excessive Solder	5
Testing Defects	Proof Test Break	5
Component Defects	Wrong Component	5

Close